

Report 07/1696

October 8th, 2007

Page 1/1

Customer: Mirak Limited  
PO box 33-217  
Barrington  
CHRISTCHURCH

P1266

### Compliance Certificate

**Appliance:** Mirak Evacuated Tube Solar Collector Model: 8VAC-R-084

**Standard Applied** Type tests for collectors per AS/NZS2712:2002

**Full Report Ref.:** 07/1680

#### Compliance

On the basis of the results given in report 07/1680 the unit tested complies with the requirements of the AS/NZS 2712:2002 for type tests applicable to collectors. As the impact resistance test was not applied we note the standard requires that in New Zealand, the collector shall have a permanent marking stating "THIS COLLECTOR HAS NOT PASSED THE AS/NZS 2712 IMPACT TEST".

We note that the test result applies only to the item tested which is described in the report. Any modifications to the equipment as tested may invalidate the compliance results.



Our report 07/1680 gives details of the appliance, the assessment and the results obtained.

#### **This report:**

Prepared by: P. Wilkie

Approved by: W.S. Webley

Release Date:

  
\_\_\_\_\_  
  
\_\_\_\_\_  
9-10-07

This report must not be reproduced except in full. Results are based on material and information supplied by the client. Applied Research Services Ltd shall not be liable in respect of any loss or damage (including consequential loss or damage) resulting from the use of reports prepared by them. Results issued in electronic form are subject to confirmation by issue of final report.